

## Quick Directions for Use of Planix Planimeter

1. Plug in and press “on” button
2. press “unit” button, toggle between units of measurement
3. Enter map scale information;
  - a. Press “1” then “scale” to set the map scale 1:1, measuring directly in map units (e.g. sq. cm)
  - b. Press “10000” then “scale” to set the map scale 1:10000, measuring directly in ground units (e.g. sq. m or sq. km)
  - c. Press “24000” then “scale” to set the map scale 1:24000, measuring directly in ground units (e.g. sq. m or sq. km)
4. Press “start” to begin measuring polygon areas
5. Trace outline of polygon in a clockwise direction; Press “end” when finished
6. Repeat, trace outline of polygon in a clockwise direction; Press “end” when finished
7. Repeat, trace outline of polygon in a clockwise direction; Press “end” when finished
8. Once you measured 3 replicates of polygon area, press “average” to average the 3 measurements in steps 5-7.
9. Press “off” and “on” to reset instrument, repeat steps to measure next polygon